

Adapter and connector removal tool

Helps to remove connectors and adapters from ODF with limited space

Design

- SC simplex
- SC duplex
- MI
- MD connector extraction tool when blow-fiber in duct 4 and 5mm

Articles 3



	weids	RIPER
Article name	•	
Removal tool for SC connectors and simplex adapter (LM-5400) 21136	_	
Removal tool for SC connectors and duplex adapter (LM-5268) 21137	_	
Removal tool for MU connectors (LM-5363) 21138	0.1	